




Photo Album for Marion Fire Department, IA Job 37320 January 20, 2023

In this report the cab remained staged to begin initial assembly, the frame build continued, the pump house is staged, and the body completed the paint process. In the next report the cab may begin initial assembly, the frame may be staged, the pump house may remain staged, and the body may begin initial assembly.



DSC05030



DSC05031



DSC05032



DSC05033



DSC05034



DSC01361



DSC01362



DSC01363



DSC01364



DSC01365



DSC04822



DSC04823



DSC04824



DSC04743



DSC04744



DSC04745



DSC04746



DSC04747



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

