Photo Album for Marion Fire Department, IA Job 37320 January 27, 2023


In this report the cab started initial assembly, the frame build continued, the pump house is staged, and the body is staged for initial assembly. In the next report the cab may continue initial assembly, the frame may be staged, the pump house may remain staged, and the body may begin initial assembly.





DSC01251





DSC01253 © 2005 - 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



DSC01252





DSC01275





DSC01277 © 2005 - 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



Find us on Facebook

f





DSC01279





DSC04366 © 2005 - 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



DSC04365





DSC04350





DSC04352 © 2005 - 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









DSC04354





http://reliantfire.com/



An Oshkosh Corporation Company



©2005- 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956

