



Photo Album for Jesup Fire Department, IA Job 37538 March 10, 2023

In this report your cab completed paint and started initial assembly, the frame build continued, and the body completed the paint process. In the next report your cab may continue initial assembly, the frame build may continue, and your body may remain staged for initial assembly.



DSC01590



DSC01591




DSC01592



DSC01593



DSC01594



DSC04976




DSC04977



DSC04978



DSC04979



DSC04980



DSC04981



DSC04982



DSC04983



DSC05814



DSC05815



DSC05816



DSC05817



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

