



# Photo Album for Denison Fire Department, IA Job 37720 May 12, 2023

In this report your cab continued the paint process, your pump house began initial assembly, and the body completed fabrication and was staged. In the next report your cab may continue through paint, the pump house may continue initial assembly, and the body may begin the paint process.



DSC04614



DSC04615



DSC04616



DSC04617





DSC04618



DSC07140



DSC07141



DSC07142






DSC07143



DSC07144



DSC04861



DSC04862



DSC04863



DSC04864



DSC04865





<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

