



Photo Album for Denison Fire Department, IA Job 37720 May 19, 2023

In this report your cab made progress through paint and was staged, your pump house was painted, and the body remained staged. In the next report your cab may remained staged, the pump house may continue initial assembly, and the body may begin the paint process.



DSC04679



DSC04680




DSC04681



DSC04682



DSC04683



DSC07114



DSC07115



DSC07116



DSC07117



DSC07118



DSC04790



DSC04791



DSC04792



DSC04793



DSC04794



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

