



Photo Album for Denison Fire Department, IA Job 37720 May 26, 2023

In this report your cab remained staged, your pump house continued initial assembly, and the body began the paint process. In the next report your cab may begin initial assembly, the pump house may be staged, and the body may continue through paint.



DSC04741



DSC04742



DSC04743



DSC04744



DSC04745



DSC07115



DSC07116



DSC07117



DSC07118



DSC07119



DSC07181



DSC07182



DSC07183



DSC07184



DSC07185



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

