



# Photo Album for Denison Fire Department, IA Job 37720 June 02, 2023

In this report your cab began initial assembly, the frame build began, the pump house completed initial assembly and was staged, and the body continued through paint. In the next report your cab may continue initial assembly, the pump house may remain staged, and the body may continue the paint process.



DSC01419



DSC01420




DSC01421



DSC01422



DSC01423



DSC01000



DSC01001



DSC01002



DSC01003



DSC01004



DSC01171



DSC01172



DSC01173



DSC01174



DSC01175



DSC04935



DSC04936



DSC04937



DSC04938



DSC04939



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

