




Photo Album for Denison Fire Department, IA Job 37720 June 09, 2023

In this report your cab continued initial assembly, the frame build continued, the pump house remained staged, and the body completed paint and was staged. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may remain staged, and the body may remain staged to begin initial assembly.



DSC01040



DSC01041



DSC01042



DSC01043



DSC01044



DSC04815



DSC04816



DSC04817



DSC04818



DSC04819



DSC04820



DSC04821



DSC01053



DSC01054



DSC01055



DSC01056



DSC01057



DSC04708



DSC04709



DSC04710



DSC04711



DSC04712



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

