

In-Production Photo Report for City of Cedar Rapids Fire Department, IA Job# 37912

Status as of September 22, 2023

In this report your cab was staged to continue through paint, the pump house structure was fabricated, and the body continued fabrication. In the next report the cab may continue through paint, the pump house structure may begin initial assembly, and the body may complete the fabrication process.





DSC03177



DSC03178



DSC03179




DSC00076



DSC00077



DSC00078



DSC00046



DSC00047



DSC00048



DSC00049



DSC00050



<https://reliantfire.com/>



An Oshkosh Corporation Company