


In-Production Photo Report for Kilbourn Volunteer Fire Department, WI Job# 38102

Status as of September 15, 2023

In this report your cab continued the paint process, the pump house completed initial assembly, the torque box remained staged (no photos), the front body module was fabricated and staged, and the rear body module remained staged. In the next report your cab may continue through paint, the pump house may remain staged, the front body module may begin the paint process, the torque box may remain staged, and the rear body module may begin the paint process.





DSC01316




DSC01317



DSC01318



DSC01319



DSC00295




DSC00296



DSC00297




DSC00298



DSC00299



DSC00300



DSC00045



DSC00046



DSC00047



DSC03286



DSC03287



DSC03288



DSC03289



<https://reliantfire.com/>



An Oshkosh Corporation Company