In-Production Photo Report for

City of Cedar Rapids Fire Department, IA Job# 37912

Status as of October 06, 2023

In this report your cab continued the paint process while both the pump house structure and body remained staged. In the next report the cab may be staged to begin initial assembly, the pump house structure may begin initial assembly, and the body may remain staged to begin in paint.







DSC00830



DSC00832



DSC00831



DSC00101



DSC00102



DSC03291



DSC00103



DSC03292



DSC03293



https://reliantfire.com/





An Oshkosh Corporation Company