


In-Production Photo Report for Mount Pleasant Fire Department, IA Job# 40167

Status as of January 26, 2024

In this report the cab was installed on the frame, the pump house began initial assembly, the torque box began initial assembly, the front body module was unavailable for photos, and the rear body began the paint process. In the next report the chassis may continue assembly, the pump house may continue initial assembly, the torque box may continue initial assembly, the front body module may be available, and the rear body module may continue through paint.





DSC00206



DSC00207



DSC00208



DSC00209



DSC00210



DSC00211



DSC00212



DSC00213



DSC00214



DSC00215



DSC00216



DSC00217



DSC00218



DSC00219



DSC00220



DSC00221



DSC00222



DSC00223



DSC00224



DSC00225



DSC00226



DSC00227



DSC00228



DSC00229



DSC00230




DSC00231



DSC00232



DSC00233



DSC00234



DSC00235



DSC00236



DSC00237



DSC00238



DSC00239



DSC00240



DSC00241



DSC00242



DSC00243



DSC00244



DSC00245



DSC00246



DSC00247



DSC00248




DSC00249



DSC00250



DSC00251



DSC00073



DSC00074



DSC00075



DSC00076



DSC00077



DSC00137



DSC00138



DSC00139




DSC00140



DSC00141



DSC00142



DSC01153



DSC01154



DSC01155



DSC01156



DSC01157



<https://reliantfire.com/>



An Oshkosh Corporation Company