

In-Production Photo Report for Shenandoah Fire Department, IA Job# 38014

Status as of January 26, 2024

In this report your cab continued through paint, the frame build continued, the pump house structure was fabricated, and the rear body module was fabricated and staged. In the next report your cab may complete paint, the frame build may continue, the pump house structure may be painted, and the body may remain staged to begin the paint process.





DSC01179



DSC01180



DSC01181



DSC00415



DSC00416



DSC00417



DSC00019



DSC00020




DSC00021



DSC00022



DSC00023



DSC03414



DSC03415



DSC03416



DSC03417



DSC03418



DSC03419



<https://reliantfire.com/>



An Oshkosh Corporation Company