

In-Production Photo Report for Saylor Township Fire Department, IA Job# 38360

Status as of February 07, 2024

In this report the cab continued initial assembly, the frame build continued, the pump house structure continued initial assembly, and the body began the paint process. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may be painted, and the body may continue through paint.





DSC00022



DSC00023



DSC00024



DSC00025



DSC00026



DSC00074



DSC00075



DSC00076



DSC00077



DSC00078



DSC03003



DSC03004




DSC03005



DSC03006



DSC03007



DSC00748



DSC00749



DSC00750



DSC00751



DSC00752



<https://reliantfire.com/>



An Oshkosh Corporation Company