


# In-Production Photo Report for Saylor Township Fire Department, IA Job# 38360

Status as of February 16, 2024

In this report the cab and pump house were installed on the frame while the body completed paint and began initial assembly. In the next report your chassis may remain staged to continue assembly, while the body may continue initial assembly.






DSC03568



DSC03569



DSC03570



DSC03571



DSC03572




DSC03573



DSC03574



DSC03575



DSC03576



DSC03577



DSC03578



DSC03579



DSC03580




DSC03581



DSC03582



DSC03583



DSC03584



DSC03585



DSC03586



DSC03587



DSC03588



DSC03589



DSC03590



DSC03591



DSC03592



DSC03593



DSC03594



DSC03595



DSC03596



DSC03597



DSC03598




DSC03599



DSC03600



DSC03601



DSC03602



DSC03603



DSC03604




DSC03605



DSC03606



DSC03607



DSC03608



DSC03609



DSC03610



DSC03611



DSC03612



DSC03613



DSC03614



DSC03615



DSC03616



DSC03617



DSC03618



DSC03619



DSC03620



DSC03621



DSC03622



DSC03623



DSC03624



DSC03625




DSC03626



DSC03627



DSC03628



DSC03538



DSC03539



DSC03540



DSC03541



DSC03542



<https://reliantfire.com/>



An Oshkosh Corporation Company