


In-Production Photo Report for Shenandoah Fire Department, IA Job# 38014

Status as of February 02, 2024

In this report your cab began initial assembly, the frame build continued, the pump house began initial assembly, and the rear body module remained staged. In the next report your cab may continue initial assembly, the frame build may continue, the pump house structure may continue initial assembly, and the body may begin the paint process.






DSC00179



DSC00180




DSC00181



DSC00182



DSC00183



DSC00101



DSC00102



DSC00103



DSC03480



DSC03481



DSC03482



DSC03483



DSC03484



DSC03254



DSC03255



DSC03256



DSC03257



DSC03258



<https://reliantfire.com/>



An Oshkosh Corporation Company