## In-Production Photo Report for Shenandoah Fire Department, IA

Status as of February 07, 2024

In this report your cab continued initial assembly, the frame build continued, the pump house continued initial assembly, and the rear body module remained staged (no photos). In the next report your cab may continue initial assembly, the frame build may continue, the pump house may complete initial assembly, and the body may begin the paint process.



Job# 38014





DSC00031



DSC00033



DSC00032



DSC00034



DSC00035



DSC00065



DSC00064



DSC00066



DSC00067



DSC03065



DSC00068



DSC03066




DSC03067



DSC03069



DSC03068



DSC00774







DSC00776



https://reliantfire.com/





**An Oshkosh Corporation Company**