

In-Production Photo Report for Shenandoah Fire Department, IA Job# 38014

Status as of February 16, 2024

In this report your cab was installed on the frame, the pump house continued initial assembly, the torque box began initial assembly, the front body module was unavailable for photos, and the rear body module began the paint process. In the next report the pump house may complete initial assembly and be installed on the frame along with the torque box, the front body module may be available, and the body may complete paint and begin initial assembly.





DSC00148



DSC00149



DSC00150



DSC00151



DSC00152



DSC00153



DSC00154



DSC00155



DSC00156



DSC00157



DSC00158



DSC00159



DSC00160



DSC00161



DSC00162



DSC00163



DSC00164



DSC00165



DSC00166



DSC00167



DSC00168



DSC00169



DSC00170



DSC00171



DSC00172



DSC00173



DSC00174



DSC00175



DSC00176




DSC00177



DSC00178




DSC00179



DSC00180



DSC00181



DSC00182



DSC00183



DSC00184



DSC00185



DSC00186



DSC00187



DSC00188



DSC00189



DSC00190



DSC00191



DSC00192



DSC00193



DSC00194




DSC00195



DSC00196



DSC00197



DSC00069



DSC00070



DSC00071



DSC00072



DSC00073



DSC00074



DSC00075



DSC00076



DSC00077



DSC00078



DSC00918



DSC00919



DSC00920



DSC00921



DSC00922



<https://reliantfire.com/>



An Oshkosh Corporation Company