


# In-Production Photo Report for Shenandoah Fire Department, IA Job# 38014

Status as of February 23, 2024

In this report the torque box was installed followed by the front and rear body modules being merged with the chassis while assembly continued. In the next report your apparatus may complete initial assembly and begin final assembly.





DSC03340



DSC03341



DSC03342



DSC03343



DSC03344



DSC03345



DSC03346



DSC03347



DSC03348



DSC03349



DSC03350



DSC03351



DSC03352



DSC03353



DSC03354



DSC03355



DSC03356



DSC03357



DSC03358



DSC03359



DSC03360




DSC03361



DSC03362



DSC03363



DSC03364



DSC03365



DSC03366




DSC03367





DSC03368



DSC03369



DSC03370




DSC03371



DSC03372



DSC03373



DSC03374



DSC03375




DSC03376



DSC03377



DSC03378



DSC03379



<https://reliantfire.com/>



An Oshkosh Corporation Company