
In-Production Photo Report for Dubuque Fire Department, IA Job# 39117 Status as of March 22, 2024

> In this report the cab continued through paint, the front body module was fabricated and began the paint process, and the rear body module began fabrication. In the next report the cab may continue the paint process, the front body module may continue through paint, and the rear body module may continue the fabrication process.










DSC00292





DSC00294

DSC00293








DSC00305

DSC00295



Pierce. DA Finish = Blue Multi-Job # 39117 TT Moluto R, Description 000 WIY. Clock # | Strip ME Hane Access Panels Air Bottle Rack Blister, Cord Reel Blister, Waterway Breaker Box Ring Ceiling Cover Celling Cover Mounting Angles Cord Reel Guide 26 78







DSC03009



DSC03010





https://reliantfire.com/

f Find us on Facebook



An Oshkosh Corporation Company