

# In-Production Photo Report for Dubuque Fire Department, IA Job# 39117

---

Status as of March 29, 2024

In this report the cab completed paint and began initial assembly, the pump house structure was fabricated and painted, the torque box was staged, the front body module was staged to continue through paint, and the rear body module completed fabrication. In the next report the cab may continue initial assembly, the pump house may begin initial assembly, the torque box may remain staged, the front body module may continue the paint process, and the rear body module may remain staged to continue through paint.






DSC00006



DSC00007



DSC00008



DSC00009





DSC00010



DSC03082



DSC03083



DSC03084






DSC03085



DSC03086



DSC03122



DSC03123





DSC03124



DSC00314




DSC00315



DSC00316





DSC03223



DSC03224



DSC03225



<https://reliantfire.com/>



An Oshkosh Corporation Company