

# In-Production Photo Report for Dubuque Fire Department, IA Job# 39117

---

Status as of April 05, 2024

In this report the cab completed initial assembly, the pump house began initial assembly, the torque box remained staged, the front body module continued the paint process, and the rear body module remained staged. In the next report the cab may remain staged, the pump house may continue initial assembly, the torque box may remain staged, the front body module may continue through paint, and the rear body module may begin the paint process.





DSC00155



DSC00156



DSC00157



DSC00158





DSC00222



DSC00223



DSC00224



DSC00225





DSC00226



DSC00145



DSC00146



DSC00147






DSC00148



DSC00149




DSC00409



DSC00410



DSC00411



DSC00447



DSC00448



DSC00449





DSC00450



DSC00451



<https://reliantfire.com/>



An Oshkosh Corporation Company