

# In-Production Photo Report for Dubuque Fire Department, IA Job# 39117

---

Status as of April 12, 2024

In this report the cab remained staged, the frame build began, the pump house completed initial assembly, the torque box remained staged, the front body module completed paint, and the rear body module completed the paint process. In the next report the cab may remain staged, the frame build may continue, the pump house, torque box and front body module may remain staged, and the rear body module may remain staged to begin initial assembly.





DSC00381



DSC00382




DSC00383



DSC00384



DSC00385



DSC01095



DSC01096



DSC01097




DSC01098



DSC01099



DSC01100



DSC01101



DSC00453



DSC00454



DSC00455



DSC00190




DSC00191



DSC00192



DSC00193



DSC00194



DSC03275



DSC03276



DSC03277



DSC00915



DSC00916



DSC00917



DSC00918



DSC00919





<https://reliantfire.com/>



An Oshkosh Corporation Company