

In-Production Photo Report for Dubuque Fire Department, IA Job# 39117

Status as of April 19, 2024

In this report the cab remained staged, the frame build continued, the pump house was staged, the torque box remained staged (no photos), and the front and rear body modules remained staged. In the next report the cab and pump house may be installed on the frame, the torque box may begin initial assembly, the front body module may remain staged, and the rear body module begin initial assembly.





DSC00319



DSC00320



DSC00321



DSC00482



DSC00483



DSC00484



DSC00485



DSC00486



DSC00487



DSC00488



DSC00489



DSC00390



DSC00391




DSC00392



DSC00844



DSC00845



DSC00777



DSC00778



DSC00779



DSC00780



DSC00781



<https://reliantfire.com/>



An Oshkosh Corporation Company