
In-Production Photo Report for Dubuque Fire Department, IA Job# 39117 Status as of April 25, 2024

In this report the cab, pump house, and torque box were installed on the frame while the front body module remained staged, and the rear body module began initial assembly. In the next report the chassis may be staged to continue assembly, the front body module may remain staged, and the rear body module may continue initial assembly.









DSC03181





DSC03184








DSC03185




DSC03186











DSC03456





https://reliantfire.com/

f Find us on Facebook



An Oshkosh Corporation Company