In-Production Photo Report for Wauwatosa Fire Department, WI Job# 38821 Status as of April 19, 2024

> In this report your cab completed paint and began initial assembly, the frame build began, the transverse compartment was fabricated and began the paint process, and the body began fabrication. In the next report your cab may continue initial assembly, the frame build may continue, the transverse compartment may continue through paint, and the body may continue the fabrication process.









DSC00331














DSC00356







DSC00360









DSC00761











https://reliantfire.com/

f Find us on Facebook



An Oshkosh Corporation Company