


In-Production Photo Report for Wauwatosa Fire Department, WI Job# 38821

Status as of April 25, 2024

In this report your cab was installed on the frame, the transverse compartment was staged to continue the paint process, the torque box was staged, and the body completed fabrication. In the next report your chassis may continue initial assembly, the transverse compartment may continue through paint, the torque box may begin initial assembly, and the body may begin the paint process.






DSC00119



DSC00120



DSC00121



DSC00122



DSC00123



DSC00124



DSC00125



DSC00126



DSC00127



DSC00128



DSC00129




DSC00130



DSC00131




DSC00132



DSC00697



DSC00698



DSC03173



DSC03174



DSC03175



DSC00721



DSC00722



DSC00723



DSC00724



DSC00725



<https://reliantfire.com/>



An Oshkosh Corporation Company