



In-Production Photo Report for Dubuque Fire Department, IA Job# 39117

Status as of May 10, 2024

In this report final assembly continued. In the next report your apparatus may continue final assembly.





DSC03376



DSC03377



DSC03378



DSC03379



DSC03380



DSC03381



DSC03382



DSC03383



DSC03384



DSC03385



DSC03386



DSC03387




DSC03388



DSC03389



DSC03390



DSC03391



DSC03392



DSC03393



DSC03394



DSC03395



DSC03396



DSC03397



DSC03398




DSC03399




DSC03400



DSC03401




DSC03402



DSC03403



DSC03404




DSC03405



DSC03406



DSC03407



DSC03408



DSC03409



DSC03410



DSC03411



DSC03412



DSC03413



DSC03414



DSC03415



DSC03416



DSC03417



DSC03418



DSC03419



DSC03420



DSC03421



DSC03422



DSC03423



DSC03424




DSC03425



DSC03426



DSC03427



DSC03428



DSC03429



DSC03430



DSC03431



DSC03432



DSC03433



<https://reliantfire.com/>



An Oshkosh Corporation Company