


In-Production Photo Report for Fennimore Fire Department, WI Job# 38721

Status as of May 10, 2024

In this report your chassis remained staged while the body completed fabrication and began the paint process. In the next report the chassis may remain staged to continue assembly while the body may continue the paint process.





DSC03177



DSC03178



DSC03179



DSC03180



DSC03181



DSC03182



DSC03183




DSC03184



DSC03185



DSC03186



DSC03187



DSC03188



DSC03189




DSC03190



DSC03191



DSC03192



DSC03193



DSC03194



DSC03195



DSC03196



DSC03197



DSC03198



DSC03199



DSC03200



DSC03201



DSC00271




DSC00272



DSC00273



DSC00274



DSC00275



DSC00276



DSC00277



<https://reliantfire.com/>



An Oshkosh Corporation Company