In-Production Photo Report for Monroe Fire Department, WI Job# 39009 Status as of May 17, 2024

> In this report your cab completed paint and was staged, the frame build began, the front body module was fabricated, and the rear body module began fabrication. In the next report your cab may remain staged to begin initial assembly, the frame build may continue, the front body module may begin the paint process, and the rear body module may continue the fabrication process.











DSC00389









DSC00448





DSC00722





DSC00056





DSC00058





https://reliantfire.com/

f Find us on Facebook



An Oshkosh Corporation Company