

In-Production Photo Report for Monroe Fire Department, WI Job# 39009

Status as of May 24, 2024

In this report your cab completed initial assembly, the frame build continued, the pump house structure was painted, the torque box was staged, the front body module was unavailable for photos, and the rear body module completed fabrication. In the next report your cab may remain staged, the frame build may continue, the pump house may continue initial assembly, the torque box may remain staged, the front body module may be available, and the rear body module may remain staged to begin the paint process.





DSC00017



DSC00018



DSC00019



DSC00059



DSC00060



DSC00061



DSC03089



DSC03090



DSC03091



DSC03092



DSC03093



DSC03124



DSC03126



DSC03127



DSC03128



DSC03129



DSC03576



DSC03577



DSC03578



DSC03579



DSC03580



<https://reliantfire.com/>



An Oshkosh Corporation Company