


In-Production Photo Report for Wauwatosa Fire Department, WI Job# 38821

Status as of May 03, 2024

In this report the chassis was staged for torque box[®] installation, the torque box began initial assembly, the transverse compartment completed paint, and the body completed the paint process. In the next report the torque box may be merged with the chassis followed by the transverse compartment being installed, and the body may begin initial assembly.







DSC03230




DSC03231



DSC03232



DSC03233



DSC03234



DSC03235



DSC03236




DSC03237



DSC03238



DSC03239



DSC03240



DSC03241



DSC03242



DSC03243



DSC03244



DSC03245



DSC00587



DSC00588



DSC00589



DSC00590



DSC00591



DSC00562



DSC00563



DSC00564



DSC00565



DSC00566



<https://reliantfire.com/>



An Oshkosh Corporation Company