In-Production Photo Report for

Wauwatosa Fire Department, WI Job# 38821

Status as of May 17, 2024


In this report the body completed initial assembly and was installed on the chassis followed by the start of final assembly, and the aerial device arrived and began initial assembly. In the next report your apparatus may continue final assembly while your aerial device may continue initial assembly.







DSC03251



DSC03253



DSC03252



DSC03254



DSC03255




DSC03257




DSC03256



DSC03258



DSC03259



DSC03261



DSC03260



DSC03262



DSC03263



DSC03265



DSC03264



DSC03266



DSC03267



DSC03269



DSC03268



DSC03270



DSC03271



DSC03273



DSC03272



DSC03274



DSC03275




DSC03277



DSC03276



DSC03278



DSC03279



DSC03281



DSC03280



DSC03282



DSC03283



DSC00812



DSC03284



DSC00813







DSC00815



https://reliantfire.com/





An Oshkosh Corporation Company