

In-Production Photo Report for


Ames Fire Department, IA

Job# 39657

Status as of June 21, 2024

In this report your cab completed paint and began initial assembly, the frame build continued, the pump house began initial assembly, and the body began fabrication. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may complete the fabrication process.





DSC01376



DSC01377




DSC01378



DSC01379



DSC01380



DSC01389



DSC01390



DSC01391




DSC04451



DSC04452



DSC04453



DSC03153



DSC03154



DSC03155



DSC03156



DSC03157



<https://reliantfire.com/>



An Oshkosh Corporation Company