

In-Production Photo Report for Monroe Fire Department, WI Job# 39009

Status as of May 31, 2024

In this report your cab was staged, the frame build continued, the pump house continued initial assembly, the torque box remained staged, the front body module remained unavailable for photos, and the rear body module was staged to begin the paint process. In the next report your cab may remain staged, the frame build may continue, the pump house may continue initial assembly, the torque box may remain staged, the front body module may be available, and the rear body module may begin the paint process.





DSC00075



DSC00076



DSC00077



DSC00181



DSC00182



DSC00183



DSC03097



DSC03098



DSC03099



DSC03100



DSC03101



DSC03120




DSC03121



DSC03122



DSC03123



DSC01085



DSC01086



DSC01087



DSC01088



DSC01089



<https://reliantfire.com/>



An Oshkosh Corporation Company