

In-Production Photo Report for Monroe Fire Department, WI Job# 39009

Status as of June 07, 2024

In this report your cab remained staged, the frame build continued, the pump house completed initial assembly, the torque box was unavailable for photos, the front body module painted then staged, and the rear body module began the paint process. In the next report your cab may remain staged, the frame build may continue, the pump house may be staged, the torque box may be available for photos, the front body module may remain staged, and the rear body module should continue through paint.





DSC00114



DSC00115



DSC00116



DSC00177



DSC00178



DSC00179



DSC00183



DSC00184



DSC00185




DSC01014



DSC01015



DSC01016



DSC00861



DSC00862



DSC00863



DSC00864



DSC00865



<https://reliantfire.com/>



An Oshkosh Corporation Company