


In-Production Photo Report for Norway Fire Department, WI Job# 41371

Status as of June 21, 2024

In this report your cab completed fabrication and began the paint process, the frame build began, the pump house started initial assembly, and the body was fabricated and staged. In the next report your cab may continue through paint, the frame build may continue, the pump house may be painted, and the body may remain staged to begin the paint process.





DSC01078



DSC01079



DSC01080



DSC00155



DSC00156



DSC00157



DSC00158




DSC00159



DSC00160



DSC00161



DSC04435



DSC04436




DSC04437



DSC04438



DSC04439



DSC03204



DSC03205



DSC03206



DSC03207



DSC03208



<https://reliantfire.com/>



An Oshkosh Corporation Company