

In-Production Photo Report for


Ames Fire Department, IA

Job# 39657

Status as of July 12, 2024

In this report your cab completed initial assembly and was installed on the frame, the pump house completed initial assembly, and the body completed paint and began initial assembly. In the next report the pump house may be merged with the chassis while assembly may continue, and the body may continue initial assembly.





DSC00060



DSC00061



DSC00062



DSC00063



DSC00064



DSC00065



DSC00066



DSC00067



DSC00068



DSC00069



DSC00070



DSC00071



DSC00072



DSC00073



DSC00074



DSC00075



DSC00076



DSC00077



DSC00078



DSC00079



DSC00080



DSC00081



DSC00082



DSC00083



DSC00084



DSC00085



DSC00086



DSC00087



DSC00088



DSC00089



DSC00090




DSC00091



DSC00092



DSC00093



DSC00094



DSC00095



DSC00096



DSC00097



DSC00098



DSC00099



DSC00100



DSC00101



DSC00102



DSC00103



DSC00104



DSC00105



DSC00106



DSC00107



DSC00108



DSC00109




DSC00110



DSC00111



DSC00112



DSC00113




DSC00292



DSC00293



DSC00294



DSC03747



DSC03748



DSC03749



DSC03750



DSC03751



DSC03752



<https://reliantfire.com/>



An Oshkosh Corporation Company