

In-Production Photo Report for Marion Fire Department, IA Job# 41388

Status as of July 19, 2024

In this report your cab completed fabrication and was staged to begin in paint while the pump house structure was fabricated. In the next report your cab may begin the paint process while the pump house structure may remain staged.





DSC00439



DSC00440



DSC00441



DSC00442



DSC00443



DSC04040



DSC04041



<https://reliantfire.com/>



An Oshkosh Corporation Company