

In-Production Photo Report for


Marion Fire Department, IA

Job# 41388

Status as of July 26, 2024

In this report your cab began the paint process while the pump house structure remained staged. In the next report your cab should continue through paint while the pump house structure may remain staged.





DSC00010



DSC00011



DSC00012



DSC00013



DSC00014



DSC03044



DSC03045



<https://reliantfire.com/>



An Oshkosh Corporation Company