


In-Production Photo Report for Marion Fire Department, IA Job# 41388

Status as of August 02, 2024

In this report your cab continued through paint, the pump house structure remained staged, and the body began fabrication. In the next report your cab may complete the paint process, the pump house structure may remain staged, and the body may continue the fabrication process.





DSC01036



DSC01037



DSC01038



DSC01039



DSC01040




DSC03043



DSC03044



DSC03045



DSC03034



DSC03035



DSC03036



DSC03037



DSC03038



<https://reliantfire.com/>



An Oshkosh Corporation Company