

In-Production Photo Report for Marion Fire Department, IA Job# 41388

Status as of August 09, 2024

In this report your cab completed paint, the frame build began, the pump house began initial assembly, and the body completed fabrication. In the next report your cab may remain staged to begin initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may begin the paint process.





DSC00266



DSC00267



DSC00268



DSC00339



DSC00340



DSC00341



DSC00342



DSC00343



DSC00344



DSC00345



DSC03170



DSC03171




DSC03172



DSC03173



DSC03174



DSC00990



DSC00991



DSC00992



DSC00993



DSC00994



<https://reliantfire.com/>



An Oshkosh Corporation Company