


In-Production Photo Report for Marion Fire Department, IA Job# 41388

Status as of August 15, 2024

In this report your cab completed initial assembly and was installed on the frame, the pump house completed initial assembly and was staged, and the body completed the paint process and began initial assembly. In the next report the pump house may be merged with the chassis while assembly may continue, and the body may continue initial assembly.





DSC00265



DSC00266




DSC00267




DSC00268



DSC00269



DSC00270



DSC00271



DSC00272



DSC00273




DSC00274




DSC00275




DSC00276




DSC00277




DSC00278



DSC00279



DSC00280



DSC00281



DSC03626



DSC03627



DSC03628



DSC03629



DSC03630



<https://reliantfire.com/>



An Oshkosh Corporation Company