


# In-Production Photo Report for Marion Fire Department, IA Job# 41388

Status as of August 23, 2024

In this report the pump house and body were merged with the chassis while assembly continued.

In the next report your apparatus may complete initial assembly and begin final assembly.





DSC00664



DSC00665



DSC00666



DSC00667





DSC00668



DSC00669



DSC00670



DSC00671



DSC00672



DSC00673



DSC00674



DSC00675





DSC00676



DSC00677



DSC00678



DSC00679




DSC00680



DSC00681



DSC00682




DSC00683






DSC00684



DSC00685



DSC00686



DSC00687



DSC00688



DSC00689



DSC00690



DSC00691





DSC00692



DSC00693



DSC00694



DSC00695





DSC00696



DSC00697



DSC00698



DSC00699





DSC00700



DSC00701



DSC00702



DSC00703






DSC00704



DSC00705



DSC00706



DSC00707





DSC00708




DSC00709



DSC00710



DSC00711



DSC00712



DSC00713



DSC00714



DSC00715





DSC00716



DSC00717



<https://reliantfire.com/>



An Oshkosh Corporation Company