

# In-Production Photo Report for Urbandale Fire Department, IA Job# 38886

---

Status as of August 23, 2024

In this report your cab completed initial assembly and was installed on the frame, the torque box arrived and began initial assembly, the forward body module was fabricated, and the rear body module began the paint process. In the next report the chassis may remain staged to continue assembly, the torque box may continue initial assembly, the forward body module may begin the paint process, and the rear body module should continue through paint.





DSC00071



DSC00072



DSC00073



DSC00074



DSC00075



DSC00076



DSC00077



DSC00078



DSC00079



DSC00080



DSC00081



DSC00082



DSC00083



DSC00084



DSC00085



DSC00086



DSC00087



DSC00088



DSC00089



DSC00090



DSC00091




DSC00092



DSC00093



DSC00094



DSC00095



DSC00096



DSC00097



DSC00098



DSC00099



DSC00100



DSC00101




DSC00102




DSC00103



DSC00104




DSC00105



DSC00106



DSC00107



DSC00108



DSC00109



DSC00110



DSC00111



DSC00112



DSC00113



DSC00114



DSC00115




DSC00116



DSC00117



DSC00118



DSC00119



DSC00120



DSC00121



DSC00122



DSC00123



DSC00124



DSC00125



DSC00126



DSC00127



DSC00128



DSC00129



DSC03215




DSC03216




DSC03217



DSC03218



DSC03219



DSC01006



DSC01007




DSC01008



DSC01009



DSC01010



DSC00988



DSC00989



DSC00990



DSC00991



DSC00992



<https://reliantfire.com/>



An Oshkosh Corporation Company