


In-Production Photo Report for Urbandale Fire Department, IA Job# 38886

Status as of August 30, 2024

In this report the torque box was being installed on the chassis, the forward body module began the paint process, and the rear body module completed paint and began initial assembly. In the next report the chassis may be staged to continue assembly, the forward body module may continue through paint, and the rear body module may continue initial assembly.





DSC04033



DSC04034



DSC04035



DSC04036




DSC04037



DSC04038



DSC04039




DSC04040



DSC04041



DSC04042



DSC00037



DSC00038



DSC00039



DSC04594



DSC04595



DSC04596



DSC04597



DSC04598



<https://reliantfire.com/>



An Oshkosh Corporation Company