

In-Production Photo Report for Urbandale Fire Department, IA Job# 38886

Status as of September 06, 2024

In this report the chassis was staged to continue assembly, the forward body continued through paint, and the rear body module continued initial assembly. In the next report the chassis may remain staged to continue assembly, the forward body module may continue the paint process, and the rear body module may continue initial assembly.





DSC00741



DSC00742



DSC00743



DSC00744



DSC00745



DSC00746



DSC00747



DSC00748



DSC00749



DSC00750



DSC00751



DSC00752



DSC00753



DSC00754



DSC00755



DSC01011



DSC01012



DSC01013



DSC03823



DSC03824



DSC03825



DSC03826



DSC03827



<https://reliantfire.com/>



An Oshkosh Corporation Company