

In-Production Photo Report for Johnston Grimes Metropolitan Fire Department, IA Job# 38707

Status as of October 25, 2024

In this report your cab completed paint and began initial assembly, the pump house structure was painted, the torque box arrived and was staged, and the rear body module began fabrication. In the next report your cab may continue initial assembly, the pump house may begin initial assembly, the torque box may remain staged, and the rear body module may continue the fabrication process.





DSC00375



DSC00376



DSC00377



DSC00378



DSC00379



DSC03089



DSC03090




DSC03091



DSC03092



DSC03093



DSC03000



DSC03001




DSC03002



DSC03003



DSC03004



DSC03055



DSC03056



DSC03057



DSC03058



DSC03059



<https://reliantfire.com/>



An Oshkosh Corporation Company