

In-Production Photo Report for Evansville Fire District, WI Job# 38884

Status as of November 22, 2024

In this report your cab completed initial assembly and was installed on the frame, the pump was painted, and the body completed paint and began initial assembly. In the next report your chassis may be staged to continue assembly, the pump house may continue initial assembly, and the body may continue initial assembly.





DSC00094



DSC00095



DSC00096



DSC00097



DSC00098



DSC00099



DSC00100



DSC00101



DSC00102




DSC00103



DSC00104




DSC00105



DSC03012



DSC03013



DSC03014



DSC03015



DSC03016



DSC03970



DSC03971



DSC03972



DSC03973



DSC03974



<https://reliantfire.com/>



An Oshkosh Corporation Company