


In-Production Photo Report for Ankeny Fire Department, IA Job# 38806-02

Status as of January 10, 2025

In this report your cab and pump house completed initial assembly and were installed on the frame while the body completed the paint process. In the next report your chassis may continue assembly while the body may begin initial assembly.






DSC03423



DSC03424



DSC03425



DSC03426




DSC03427



DSC03428



DSC03429



DSC03430



DSC03431



DSC03432



DSC03433



DSC03434



DSC03435



DSC03436



DSC04162



DSC04163



DSC04164



DSC04165



DSC04166



<https://reliantfire.com/>



An Oshkosh Corporation Company